# PENKO Engineering B.V.

Your Partner for Fully Engineered Factory Solutions



How to... Calibrate the FLEX 2100, FLEX or FLEX 2ch. – 4ch.



# **Table of Contents**

| Set the parameters   | . 3 |
|--|-----|
| How to calculate the step size and decimal point for your installation | . 5 |
| For certified installations  | . 5 |
| For Industrial installations   | . 6 |



Before you can calibrate the FLEX some parameters has to be set first.

# Set the parameters

Go to **Menu**  $\rightarrow$  **System Setup**  $\rightarrow$  **Indicator Setup**  $\rightarrow$  **Indicator.** You need to fill in the **TAC** code (the TAC code is the number of times a parameter has been edited). The code can be found in the top right corner of the FLEX (red arrow). Fill in the code and press **OK**.

|                                   |        |          |      | 707L0000005E                 |
|-----------------------------------|--------|----------|------|------------------------------|
| Ente                              | er TAC | code     |      | TAC:00000065<br>CAL:00000100 |
| TAC code                          |        | <u>0</u> |      |                              |
| Min: -999999999<br>Max: 999999999 | 1      | 2        | 3    |                              |
|                                   | 4      | 5        | 6    |                              |
|                                   | 7      | 8        | 9    |                              |
|                                   | 0      |          | С    |                              |
| X Cancel                          |        |          | 🖌 ok |                              |
| PENKO                             |        |          |      | INDICATOR / CONTROLLER       |



Here you can edit the **Name** and **Unit label** of the FLEX.

**Name:** give the Indicator a name.

**Unit:** fill in the weighing unit, for example: g, kg, ton, lbs. or liter.

|            | Indicator | parameters | TAC:<br>CAL: | 00000065<br>00000100 |
|------------|-----------|------------|--------------|----------------------|
| Name       |           | Weighe     | er           | <b>→</b><br>EDIT     |
| Unit label | -         | kg         |              | EDIT                 |
|            |           | Forma      | tting        |                      |
|            |           | MultiRange | e/Inte       | rval                 |
|            |           |            |              |                      |
| 🗙 Cancel   |           | » Next     | 🖋 0 E        |                      |
|            |           |            | INDIC        | ATOR / CONTROLLER    |

Press Formatting.

Here you can edit the **Step** and **Decimal point** of the FLEX. Click **OK** to save.



# How to calculate the step size and decimal point for your installation

# For certified installations

In our example we have a bunker with 3 \* 200kg C3 load cells. The load of the installation itself is 50kg (dead load). The maximum amount we want to weigh is 150kg. The dead load and the maximum weighing amount must be well below the maximum capacity of the load cells combined.

So what is the smallest step size I can choose, and where to place the decimal point?

First of all we need to know the following specifications of the load cell (contact your load cell manufacture for this information):

| Accuracy class                                | C3    |
|---|-------|
| Maximum no. of intervals                      | 3000  |
| Utilization for most load cells in percentage | 33,3% |

The Utilization is a percentage of the maximum capacity of the load cell. The smaller the Utilizations the more accurate the load cell can be calibrated, and there for a smaller step size and decimal point can be selected.

The total capacity of the 3 load cells is 600kg. The utilization is 33,3%, so 33,3% of 600kg is 200kg.

Divide 200kg by 3000 (interval amount) the answer is 0,06kg. This is the minimum step size.

The Indicator doesn't have a step size of 0,06kg, choose the first one above 0,06kg that will be step size 0,1kg (this step size will affect the last digit). The decimal point must be set to 00000.0 the weighing installation will be accurate within 00.1 kg.



|               | Formatting | TAC<br>CAI | 2:00000066<br>.:00000100 |
|---------------|------------|------------|--------------------------|
| Step          |            | 1          | +                        |
| Decimal point |            | 0,0        | +                        |
|               |            |            |                          |
|               |            |            |                          |
|               |            |            |                          |
| 🗙 Cancel      |            | V OK       |                          |
| RENKO         |            |            | ICATOR / CONTROLLER      |

#### **For Industrial installations**

We will keep the same bunker with 3 \* 200kg C3 load cells. The load of the installation itself is 50kg (dead load). The maximum amount we want to weigh is 150kg. The dead load and the maximum weighing amount must be well below the maximum capacity of the load cells combined.

So what is the smallest step size I can choose, and where to place the decimal point?

First of all we need to know the following specifications of the load cell (contact your load cell manufacture for this information):

| Accuracy class                                | C3    |
|---|-------|
| Utilization for most load cells in percentage | 33,3% |

The Utilization is a percentage of the maximum capacity of the load cell. The smaller the Utilizations the more accurate the load cell can be calibrated, and there for a smaller step size and decimal point can be selected.

For Industrial it's not necessary to look up the Maximum no. of intervals.

Maximum no. of intervals (The maximum for Industrial installations is 10000) 10000

The total capacity of the 3 load cells is 600kg. The utilization is 33,3%, so 33,3% of 600kg is 200kg.



Divide 200kg by 9000 (interval amount) the answer is 0,02kg. This is the minimum step size.

Choose step size 0,02 (this step size will affect the last digit). The decimal point must be set to 0000.00. The weighing installation will be accurate within 00.02 kg.

|               | Forma | tting        | TAC:00000066<br>CAL:00000100 |
|---------------|-------|--------------|------------------------------|
| Step          | -     | 2            | +                            |
| Decimal point | -     | 0,00         | +                            |
|               |       |              |                              |
|               |       |              |                              |
|               |       |              |                              |
| X Cancel      |       | <b>V</b> 01: |                              |
| RENKO         |       |              | NDICATOR / CONTROLLER        |



Here you can edit the **Operation Mode** and the **Max load**. And click **OK** to save the parameters.

Maxload: fill in the weight the Indicator shows as the maximum load.

For example: if you are weighing 1000kg and the maximum amount you want to be show is 1005. Fill in 1005, above this amount the Indicator will show ======.

| - |           |           |            |                |                    |
|---|-----------|-----------|------------|----------------|--------------------|
|   |           |           |            |                |                    |
|   |           | Indicator | parameters | TAC:0<br>CAL:0 | 0000065<br>0000100 |
|   | Operation | Mode 🗕    | Industr    | 1              | +                  |
|   | Max Load  |           | 100,00     | kg             | EDIT               |
|   |           |           | Stable c   | onditi         | on                 |
|   |           |           | Zero ti    | racking        |                    |
|   |           |           |            |                |                    |
|   | 🗙 Cancel  | « Prev    | » Next     | 🖌 Ok           |                    |
|   |           |           |            | INDICA         | TOR / CONTROLLER   |




#### Press on Calibration

| I           | ndicat | or Setup | <u>&gt;</u> | TAC:0000006<br>CAL:00000100 | 7        |
|-------------|--------|----------|-------------|-----------------------------|----------|
| 📮 Indicator |        | Extern   | nal         | Devices                     |          |
| Filter      |        |          |             |                             |          |
| Calibration | 1      |          |             |                             |          |
| Indicators  |        |          |             |                             |          |
| Recall      |        |          |             |                             |          |
| 🔒 Home      |        |          |             |                             |          |
|             |        |          |             | INDICATOR / COI             | NTROLLER |

You need to fill in the **CAL** code (the CAL code is the number of times a calibration point has been edited) and press **OK** to unlock the calibration. The code can be found in the top right corner of the FLEX (red arrow).



Press on Points.



If there are any calibration point in the FLEX, remove them by pressing on the **Delete** button until all the calibration point are deleted.



Calibration Points The:0000067 Calibration point added. Calibration point added. Add/Replace 0,00 kg DIT Delete 0 k MULATOR / CONTROLLER

Make sure that the scale is empty and press on **Activate**. This will calibrate the first point.

Set a weight on the scale en press on **Edit.** 

| Ca          | librati | on Poir | nts TA   | C:00000067<br>L:00000100 |  |
|-------------|---------|---------|----------|--------------------------|--|
| 1 Points    | -       |         | 0,00 kg  | +                        |  |
| Sample      |         |         | 0058053  |                          |  |
| Weight      |         | ac      | ccccc kg |                          |  |
| Weight x10  |         | ac      | ccccc kg |                          |  |
| Add/Replace |         | 0,      | 00 kg    | EDIT                     |  |
| — Delete    | + Acti  | vate    | 🖌 Ok     |                          |  |
|             |         |         |          | ICATOR / CON             |  |



Fill in the weight that is on the scale and press **OK**.

| Calib                           | ration | Poin  | ts   | TAC:00000067<br>CAL:00000101 |
|---------------------------------|--------|-------|------|------------------------------|
| Add/Replace                     |        | 10,00 | )    | kg                           |
| Min: -83886,08<br>Max: 83886,07 | 1      | 2     | 3    |                              |
|                                 | 4      | 5     | 6    |                              |
|                                 | 7      | 8     | 9    |                              |
|                                 | 0      | ,     | С    | -                            |
| 🔀 Cancel                        |        |       | 🖌 OE |                              |
| RENKG                           |        |       |      | INDICATOR / CONTROLLER       |

Press on Activate to calibrate the second point and press OK





Go back to **Home**. Now the FLEX is calibrated.

| Weigher                                 | Wei               | .ght<br>0,0                                   |                                 |  |
|---|-------------------|---|---------------------------------|--|
| Weigher<br>0,00 10,00 20<br>1 2 3 4 5 6 | Out               | 50,00 60,00 70,0<br>puts<br>05 06 07 08 01 02 | kg<br>0 80,00 100,00<br>Markers |  |
| +0+ +T+                                 | <b>∲</b> <u>○</u> | FEEK FEEV                                     | <del></del>                     |  |
| Menu                                    | 🚺 Start           | Recipe  | 🔁 Screen                        |  |
| REENING MIL                             |                   |   | INDICATOR / CON                 |  |





#### About PENKO

Our design expertise include systems for manufacturing plants, bulk weighing, check weighing, force measuring and process control. For over 35 years, PENKO Engineering B.V. has been at the forefront of development and production of high-accuracy, high-speed weighing systems and our solutions continue to help cut costs, increase ROI and drive profits for some of the largest global brands, such as Cargill, Sara Lee, Heinz, Kraft Foods and Unilever to name but a few.

Whether you are looking for a simple stand-alone weighing system or a high-speed weighing and dosing controller for a complex automated production line, PENKO has a comprehensive range of standard solutions you can rely on.

#### Certifications

PENKO sets high standards for its products and product performance which are tested, certified and approved by independent expert and government organizations to ensure they meet – and even – exceed metrology industry guidelines. A library of testing certificates is available for reference on:

http://penko.com/nl/publications\_certificates.html

#### **PENKO Professional Services**

PENKO is committed to ensuring every system is installed, tested, programmed, commissioned and operational to client specifications. Our engineers, at our weighing center in Ede, Netherlands, as well as our distributors around the world, strive to solve most weighing-system issues within the same day. On a monthly basis PENKO offers free training classes to anyone interested in exploring modern, high-speed weighing instruments and solutions. A schedule of training sessions is found on: www.penko.com/training

#### **PENKO Alliances**

PENKO's worldwide network: Australia, Belgium, Brazil, China, Denmark, Germany, Egypt, Finland, France, India, Italy, Netherlands, Norway, Poland, Portugal, Slovakia, Spain, Syria, Turkey, United Kingdom, South Africa, Slovakia Sweden, Switzerland and Singapore. A complete overview you will find on: www.penko.com/dealers

