


PENKO Engineering B.V.

Your Partner for Fully Engineered Factory Solutions



Quick Start:
1020 FMD

Table of Contents

Introduction.....	3
In the box.....	3
Needed for use	3
1 Overview	4
2 Connections	5
2.1 Power supply	5
2.2 Load cell.....	6
3 Display and keypad	7
4 First use.....	11
5 Standard factory settings.....	20
6 Menu structure	21

1020 FMD

Introduction

The PENKO 1020 FMD is a compact comprehensive Force Measurement Device.

In the box

The box contains the following items:

- 1 x 1020 FMD device
- 1 x rubber ring for mounting purpose
- 2 x clip for mounting purpose
- 1 x connector for load cell connection
- 1 x quick start manual


Needed for use

To use the 1020 FMD the following items are needed:

- Class 2 or Limited Power Source, rate 18 - 32 VDC, 0.4A@24VDC
- Load cell / Torque sensor

1020 FMD

1 Overview



Option 1:



Option 2:



1020 FMD

Number	Description
1	TFT display 320 x 240
2	Keypad
3	OPTION: None Serial + CAN bus Profibus
4	Ethernet connection
5	USB connection
6	Digital inputs (3)
7	Digital outputs (4)
8	24VDC power supply
9	OPTION: Analog output
10	Load cell connection
11	RS232/RS422 connection
12	CAN bus connection
13	Profibus connection
14	Bus termination for Profibus

2 Connections

This chapter describes the power supply and load cell connections of the 1020 FMD.

2.1 Power supply





Power the device using a Class 2 or Limited Power Source, rate 18 – 32 VDC, 0.4A@24VDC



1020 FMD

2.2 Load cell




Property	Description
Wiring	With sense
Type of sense	Passive
Excitation voltage	5 VDC
Sensitivity	0,1 $\mu\text{V}/\text{d}$
Selectable ranges	1 mV/V 1,5 mV/V 2 mV/V 2,5 mV/V 3 mV/V
Input voltage @3mV/V	-16 mV to 16 mV
A/D Conversion speed	1600/s
Max. load cell impedance	1200 Ω
Min. Load cell impedance	43,75 Ω
Max. no. of load cells 350 Ω	8
Max. no. of load cells 1000 Ω	22

1020 FMD

3 Display and keypad

The display contains the following indications:



Number	Description
1	Indicator in stable range [] Zero active [] Range/Interval active
2	Bar graph indication
3	Digital input active indication (3 inputs)
4	Digital output active indication (4 outputs)
5	Measured value
6	Type of value shown on the display (Tracking, Hold, T.I.R, Peak, Valley) *


* Display value

Tracking	Tracking value. The display follows the input signal.
Hold	Hold value. The hold value is stored every time the zero button is pressed in hold mode, and every time the input, programmed as hold, is high.
Peak	Peak hold value. This is the highest measured value.
Valley	Valley hold value. This is the lowest measured value.
T.I.R.	Total Indicated Readout value. The difference between the peak hold and valley hold value.


See next page for examples.

1020 FMD

Hold function




Peak, Valley and T.I.R. function



1020 FMD

The display indications in menu mode:



Number	Description
1	Active buttons for current menu item
2	TAC and CAL code*
3	Menu level

* TAC and CAL code

TAC stands for Traceable Access Code. A number of settings are only available after entering this code. When these settings are changed, the TAC is incremented with 1.

CAL stands for CALibration code. The calibration settings are only available after entering this code. When the calibration settings are changed, the CAL is incremented with 1.

1020 FMD

The keys have the following functions:



Tracking / Hold

Toggle between Tracking mode and Hold mode.



Peak Hold

Show Peak Hold mode.



Enter / Menu

Adjust levels. Press > 2 seconds to enter configuration menu. In menu mode, press to confirm setting.



Zero

Press to set tare/zero. Press again to reset tare/zero. In Hold mode, press to set hold value. In Peak/Valley/T.I.R mode, press to clear the stored value.



Print / Escape

Press to cancel or step back one menu item. Press from start screen to print.



Up / Increase value

From start screen, press to show T.I.R. value on the display.



Down / Decrease value

From start screen, press to show valley hold value on the display.



Left / Change position of cursor



Right / Change position of cursor



an ETC Company

1020 FMD

4 First use


For first use, the following settings are important:

- Unit indication
- Decimal point position
- Step size
- Maximum load
- Calibration


This chapter describes how to adjust these settings.

Main Menu

From the main screen, press the Enter button for 2 seconds to enter the Main Menu.



Press 2 seconds



1020 FMD

Navigate through menu

Use the Up and Down button to navigate through the menus. Use the Enter button to enter a menu item. Use the Escape button to step back a level.



Up



Down



Open menu
item



Back to
previous level

Edit a value

```
20.000 kN
Min: -8388.608 kN
Max: 8388.607 kN
```

Use the arrow buttons to edit a value. Select the digit with the Left and Right button. Increase the value with the Up button. Decrease the value with the Down button. Use the Enter button to confirm the whole value. Use the Zero button to clear the whole value.



Select
previous digit



Select next
digit



Increase
selected digit



Decrease
selected digit



Confirm
whole value



Clear whole
value




an ETC Company


1020 FMD

Edit a text

In case a text has to be edited, a keyboard appears on the screen.



Use the arrow buttons to navigate through the keyboard. Use the Enter button to select the character. Use the Zero button for backspace. Use the Peak-hold button to change the character set.







Change character set

1020 FMD



Indicator parameters

The indicator parameters can be set as follows:



Enter the TAC as shown on the right bottom corner of the screen using the arrow buttons - apply with the Enter button

1020 FMD



Here the Unit, Step size, Decimal point and Max load can be set

Unit

Set the unit of measurement, for example kN or N. This will be shown everywhere the measured force is displayed or printed.

Decimal point

Select the position of the decimal point. This setting will be used everywhere the measured force is displayed or printed.

Available options
000000
00000.0
0000.00
000.000
00.0000
0.00000

Step

Select the step size. This setting defines the scaled parts of the force value. The display value will be rounded to the nearest value with a valid step size. Available options:

1020 FMD

Available options
1
2
5
10
20
50
100
200

→ Example:

Measured value is 2005 kN.





Step size	Displayed value
1	2005
2	2006
5	2005
10	2010
20	2000
50	2000
100	2000
200	2000

Maxload

Set the force the indicator will use as maximum. If the measured force is higher than the maximum load, the display will show =====




1020 FMD

Calibration




Enter the CAL as shown on the right bottom corner of the screen using the arrow buttons - apply with the Enter button

1020 FMD




Make sure the load cell or force sensor is not loaded and is stable before pressing Enter




Make sure the load cell or force sensor is loaded with the reference weight and is stable before pressing Enter

1020 FMD



Enter the reference weight - apply with the Enter button



The device is now calibrated


Error codes:

Error code	Description	Solution
CCCCCC	No proper calibration available	Check calibration setting
UUUUUU	Underflow	Check load cell Check platform construction
OOOOOO	Overflow	Check load cell Check platform construction
=====	Display overflow; Exceed maximum display value (max. load)	Reduce load on platform


5 Standard factory settings

Description	Display	Value	Your setting
Properties	Name	...	
	Unit label	kN	
	Step	1	
	Decimal point	0,000	
	Max Load	10,009 kN	
	Sample Rate	1600/s	
Stable condition	Range	0,002 kN	
	Time	1,00 s	
Zero tracking	Range	0,000 kN	
	Step	0,000 kN	
	Time	0,00 s	
Range / Interval	Range	0 Parts	
	Max Step	1	
	Mode	Multi Range	
Filter - Overall	Overall Filter	0 dB	
Filter - Digital	Digital Filter	Static App.	
	Cutoff Frequency	1,0 Hz	
	Frequency	50 Hz	
Filter- Display	Filter Range	0,000 kN	
	Display Filter	0 dB	
	Display Rate	25 updates/s	
	Disp.Suppress	0,000 kN	


6 Menu structure



1020 FMD



1020 FMD





About PENKO

Our design expertise include systems for manufacturing plants, bulk weighing, check weighing, force measuring and process control. For over 35 years, PENKO Engineering B.V. has been at the forefront of development and production of high-accuracy, high-speed weighing systems and our solutions continue to help cut costs, increase ROI and drive profits for some of the largest global brands, such as Cargill, Sara Lee, Heinz, Kraft Foods and Unilever to name but a few.

Whether you are looking for a simple stand-alone weighing system or a high-speed weighing and dosing controller for a complex automated production line, PENKO has a comprehensive range of standard solutions you can rely on.

Certifications

PENKO sets high standards for its products and product performance which are tested, certified and approved by independent expert and government organizations to ensure they meet – and even – exceed metrology industry guidelines. A library of testing certificates is available for reference on:

http://penko.com/nl/publications_certificates.html



PENKO Professional Services

PENKO is committed to ensuring every system is installed, tested, programmed, commissioned and operational to client specifications. Our engineers, at our weighing center in Ede, Netherlands, as well as our distributors around the world, strive to solve most weighing-system issues within the same day. On a monthly basis PENKO offers free training classes to anyone interested in exploring modern, high-speed weighing instruments and solutions. A schedule of training sessions is found on: www.penko.com/training

PENKO Alliances

PENKO's worldwide network: Australia, Belgium, Brazil, China, Denmark, Germany, Egypt, Finland, France, India, Italy, Netherlands, Norway, Poland, Portugal, Slovakia, Spain, Syria, Turkey, United Kingdom, South Africa, Slovakia Sweden and Switzerland, Singapore. A complete overview you will find on: www.penko.com/dealers

